

Bolyard Residence

60 Franklin Street, Dublin, OH 43017

Photo Summary

Front Elevation (West Facing Façade)





Front Corner Elevation (North-West)



Front Yard Looking North-West (Church)



Front Corner Elevation (South-West)



Adjacent Neighbor(s) Looking South-East



Front Yard Looking South-West



Adjacent Neighbor(s) Looking North-East



Rear Corner Elevation (South-East)



Rear Elevation (East) – Project Addition Area



Rear Elevation (East)



Rear Corner Elevation (North)



Rear Corner Elevation (North-East)




Rear Corner Elevation (North-East)



Back Yard Looking North-East



Existing Roof – New to match Existing



Back Yard Looking East



Existing Roof – New to match Existing



Back Yard Looking South-East



**Existing - Stone, Sill, Stucco material
New to match Existing**



Existing rear porch stoop, concrete, stairs, treads, railing, post. New to match Existing.



Black aluminum stoop/stair railing profile. New to match Existing.