Parcel	273-000428/ 273-001707	Address	5281 Brand Rd	()HI FRA-1944-1
Year Built:	1870	Map No:	87	Photo No:	918-931 (6/25/16)
Theme:	Agriculture	Historic Use:	Agriculture/single family house	Present Use:	Single family house
Style:	Italianate	Foundation:	Stone	Wall Type:	Brick
Roof Type:	Hipped/standing seam metal	Exterior Wall:	Brick	Symmetry:	No
Stories:	2	Front Bays:	5	Side Bays:	2
Porch:	Hipped porch on façade ell, with brackets	Chimney:	3, interior	Windows:	6-over-6, Possibly historic/appropriate replacements

Description: The farmstead complex includes a house, two barns, a silo, three sheds, and a smaller building--possibly a hog house. The two-story, Italianate-style house has a T-plan footprint and is expanded by a one-story L-plan addition with a gable roof on its south elevation. The hipped roof of the brick house is sheathed in standing seam metal. A front porch is on the façade ell, which has a half-hipped roof supported by wood posts with decorative brackets and dentils. The primary entrance is on the façade of the projecting wing. It consists of paired doors with a multi-light transom above. Windows are six-over-six double-hung sashes. Façade fenestration features pediments over the openings.

Setting: The property is on the southwest corner of Brand and Coffman Rds on a large parcel with mature trees and landscaping around the house. A round-about traffic circle is located northeast of the house.

Condition: Good

Integrity: Location: Y Design: Y Setting: N Materials: Y

Workmanship: Y Feeling: Y Association: Y


Integrity Notes: The property has good integrity, although setting has been impacted by the round- about.

Historical Significance: The extant house and its outbuildings (parcel #273-001701) are listed in the NRHP as part of the Washington Township MRA, albeit under the address of 5381 Brand Rd.

District: No Contributing Status: N/A

National Register: Washington Township MRA Property Name: Asher Brand/Conine/Bower Farm







5281 Brand Rd, looking southwest

OHIO HISTORIC INVENTORY

THIS IS A FACSIMILE OF THE FORM PRODUCED BY:

DUDIN HOH SCHOOT, 1984.

OHIO HISTORIC PRESERVATION OFFICE 567 East Hudson St. Columbus, Ohio 43211-1030 614/297-2470-fax 614-297-2496



1.No. 2 County 4.Present Name(s) Franklin FRA-1944-1 CODED 3.Location of Negatives CODED City of Dublin 5. Historic or Other Name(s) Brand/Conine/Bower Farm Roll No. Picture No.(s) 6 13 - 146.Specific Address or Location 16. Thematic Association(s) 28. No. of Stories 2 5281 Brand Road agriculture + AANKLIN 29. Basement? XYes No 6a. Lot, Section or VMD Number 17. Date(s) or Period 17b. Alteration Date(s) c.1870 30. Foundation Material 18. Style or Design limestone 7.City or Village If Rural, Township & Vicinity High Style Dublin Italianate 31. Wall Construction **Elements** brick 8. Site Plan with North Arrow 18a. Style of Addition or Elements(s) 32. Roof Type & Material hip/st.seam metal 19. Architect or Engineer 33. No. of Bays DRAND/CONINE/ DOWER FRAM 19a. Design Sources Front 5 Side 34. Exterior Wall Material(s) 20. Contractor or Builder Asher Brand 35. Plan Shape rect. 21. Building Type or Plan 36. Changes Addition Altered 9. U.T.M. Reference 22. Original Use, if apparent (Explain In #42) Moved farm Quadrangle Name Hilliard 23. Present Use 37. Window Types farm 17 318280 4442850 Other Zone Easting Northing 24. Ownership Public Private 10. 38. Building Dimensions Site Building Structure Object 25. Owner's Name & Address, if known 39. Endangered? No 12. N.R. 11. On National By What? No Register? Potential? 40. Chimney Placement none observed 13. Part of Estab. 14. District No Hist Dist? Potential? 26. Property Acreage 41. Distance from and 15. Name of Established District (N.R. or Local) 27. Other Surveys in Which Included Frontage on Road 5281 BRAND RD 42 Further Description of Important Interior and Exterior Features (Continue on reverse if necessary) Well preserved mid-19th century residence with 6/6 windows, sandstone sills and lintels, dentilled cornice, original porch in front. There are additions at the rear of the house. Interior walls and fireplace have been changed and interior shutters removed. Spiral staircase is notable but cherry and walnut floors have been replaced. 43. History and Significance (Continue on reverse if necessary) Built by Asher Brand, an early settler in the area. It was also owned by Joseph Conine and was the Count Bower farm for over 50 years, beginning in 1923. The farm had 95 acres at one time and now has 3 acres. 46, Prepared by Slagle 44. Description of Environment and Outbuildings (See #52) Several farm buildings are on the site including: a 47. Organization smokehouse and summer kitchen to the rear of the house; a large barn with a concrete sile and a medium-sized 48. Date Recorded in Field barn. The outbuildings have wood siding and gabled(over) 45. Sources of Information 50. Date Revised 49. Revised by 8/75; Frank Bower (owner in 1975), Shanachie N. Recchie Historical Magazine, Dublin Historical Society, Vol.1, 50b. Reviewed by

51. Condition of Property		54. Farmstead Plan
Excellent		
Good/Fair		
Deteriorated		
Ruin		
Destroyed/Burned	Date	
52. Historic Outbuildings and Depen	ndencies	
Barn Type(s)		
Corn Crib or Shed		
Summer Kitchen		
Silo		
Smoke House		
Spring House		
lce House		
Designed landscape features		
Privy		1
Garage		l .
53. Affitiated OAI Site Number(s)		
Archaeological Feature:		
Observed	Expected on Basis of Archival	
Well	Research	
Privy	Well	
Cistern	Privy	
Foundation	Cistern	
Structural Rubble	☐ Foundation ☐ Structural Rubble	
Formal Trash Dump	Formal Trash Dump	
Other -	Other -	
42. (Cont'd)		
00000 \$55570000000		

rooflines with standing seam metal roofs. At one time the farm had 95 acres but has only about 3 acres now. The area surrounding this farm has been developed in the past few years.

43. (Cont'd)



ARCHITECTURAL REVIEW BOARD

BOARD ORDER

September 24, 2008

Land Use and Long Range Planning 5800 Shier-Rings Road Dublin, Ohio 43016-1236

Phone: 614-410-4600 Fax: 614-410-4747 Wah Site: ween dublin oh us

The Architectural Review Board took the following action at this meeting:

2. Keeler Residence 08-085ARB

5281 Brand Road Exterior Modifications

Proposal:

Architectural modifications including window repairs, new porches, and a new roof for an existing single-family residence subject to the Architectural Review process. The 1.45-acre site is located at the southwest corner of the intersection of Brand Road

and Coffman Road.

Request:

Review and approval of exterior modifications under the

provisions of the Historic Dublin Design Guidelines.

Applicant:

Frank Ronk, Contractor. Jonathan Papp, Planner.

Planning Contact:

Contact Information: (614) 410-4683, jpapp@dublin.oh.us

MOTION: William Souders made a motion, seconded by Tom Currie, to accept the original proposed exterior modification without conditions.

VOTE:

4 - 0.

RESULT:

The application was approved.

RECORDED VOTES:

Thomas Holton

Yes

Clayton Bryan

Absent

William Souders

Yes

Linda Kick

Yes

Tom Currie

Yes

STAFF CERTIFICATION

Jonathan Papp, Planner



PLANNING REPORT

ARCHITECTURAL REVIEW BOARD

SEPTEMBER 24, 2008

Phone: 614-410-4600 Fax: 614-410-4747 Web Site: www.dublia.oh.us

SECTION I - CASE INFORMATION

2. Keeler Residence 08-085ARB

5281 Brand Road Exterior Modifications

Proposal:

Architectural modifications including window repairs, new

porches, and a new roof for an existing single-family residence subject to the Architectural Review process. The 1.45-acre site is located at the southwest corner of the intersection of Brand Road

and Coffman Road.

Request:

Review and approval of exterior modifications under the

provisions of the Historic Dublin Design Guidelines.

Applicant:

Frank Ronk, Contractor. Jonathan Papp, Planner

Planning Contact:

Contact Information: (614) 410-4683, jpapp@dublin.oh.us

Case Summary

The applicant is requesting review and approval of exterior modifications that include a change in trim color, roof replacement, window refurbishment, and the replacement of two porches for a home under the review of the Architecture Review Board. Planning has evaluated this request for exterior modifications based on the *Historic Dublin Design Guidelines* and approval is recommended.

Site Description

Location

The site is a 1.45-acre site is located on the southwest corner of Brand Road and Coffman Road. The site, although not located within the formal Historic District boundaries, is subject to ARB review since it is listed in Appendix G of the Zoning Code and included on the Ohio Historical Inventory. The applicant also owns a 2.79-acre tract of land directly to the west that is not part of this review.

Site Character

The site slopes from the northeast to the southwest with the North Fork of the Indian Run creating the southern property boundary. The site contains an historic farmhouse and two outbuildings.

Historic Background

The original 1600-square-foot farmhouse was constructed in 1870 of red brick with wood accents and a metal standing seam roof. The northern façade of the original house also included

the existing porch that is constructed of wood. In the early 1900s, an addition was constructed toward the rear of the house using matching building materials. The addition included a 780-square-foot living space and a 225-square-foot single-car garage. Three wooden porches where also added with the new construction. Two were located on the eastern elevation and the third porch was located on the southern elevation of the addition.

Surrounding Zoning and Uses

This site is zoned R-1, Restricted Suburban Residential District, and PUD, Planned Unit Development District. The parcels to the south and west of the site are zoned PUD, Planned Unit Development District. A church occupies the southern property, while a multi-family residential complex is located to the west. The properties to the north and east are located in Washington Township, and contain single-family residences.

Plan Description

Overview

The applicant is proposing to restore or replace the exterior features of the current farmhouse. The original windows and masonry are to be restored and the roof replaced. The applicant is also proposing to replace the two porches on the eastern elevation.

Porches

The existing porches on the eastern façade are proposed to be replaced with porches that will match the profile and scale of the original front porch on the northern façade. The applicant is proposing to incorporate similar posts, arched brackets, and lintels. The front porch will also be updated with the new color scheme

Windows

The applicant is proposing to restore the existing windows by removing them from their sashes, and stripping the paint and glazing from the sashes and frames. All original glass will be saved and reused in the existing location. The frames will be primed and painted prior to being re-hung in their sashes. The sash color will be Glidden Quiet Light (60YY65/082), and the frames will be Valspar Olive Shale (EE2021C).

Roof

The existing standing seam metal roof will be replaced with a new standing seam metal roof. The proposed material is 24-gauge Galvalume (galvanized aluminum) panels that are 16 inches wide with 1.75-inch high standing seams. The panel is constructed with a snap-lock system for ease of installation and a strong water tight seal. The design allows for the panels to expand and contract freely, which extends the life of the roof material and substrate. The roof is proposed to be Spartan Bronze in color.

Colors

The applicant is proposing to replace the current color of the house trim, windows, and doors. The proposed colors are Olive Shale (EE2021C) by Valspar, Quiet Light (60YY65) by Glidden, and Cocoa Rose (LA216) by American Traditions. The trim around the windows and doors will use the Olive Shale and Quiet Light colors. The porch trim and the trim at the roof will use all three of the proposed colors as outlined on page CS-1 of the submitted plans.

Masonry

The proposal includes restoring the existing brick façade by cleaning the brickwork with a power washer and repointing the joints using mortar which will match the existing materials and strength.

Historic Preservation Consultant

Upon evaluation of the proposed changes, Historic Preservation Consultant Jeff Darbee has concluded that the proposed window restoration, brick cleaning, and roof replacement are acceptable and recommends approval. However, he has indicated that the two porches on the eastern facade, although comprised of different design elements from the original front porch, be maintained and repaired to tell the story of how the character of the house has been created over time (See the attached correspondence).

SECTION II – REVIEW STANDARDS:

Architectural Review Board

The Board's role in this process is defined by Code Section 153.182 (C), which requires the ARB to review the design of new structures and site improvements with respect to compatibility of the architectural style, general design, arrangement, texture, materials and color of other structures and premises within the area. Section (E) requires that the Board determine whether the proposed change will be appropriate to the preservation of the historic, architectural or environmental character of the Architectural Review District according to the criteria specified in the Code.

Evaluation and Recommendation based on the Guidelines:

The *Guidelines* identify strategies for the review and approval of building and site improvements. Numbers assigned to the guidelines reflect the order in which they appear in the table of contents of the *Historic Dublin Design Guidelines* and may appear below in a different order than listed in the *Guidelines*. Only guidelines relevant to this case are listed. The Board should consider the following guidelines to review this proposal against:

Preservation (Guidelines 2). Maintenance of the original character can be achieved by retaining and implementing procedures to ensure existing foundations, siding, masonry and commercial and residential characteristics are preserved. As residential properties are converted, the character should remain intact since it is what makes Historic Dublin a visually attractive and desirable place to live and work.

<u>Guidelines met.</u> The applicant is retaining many of the original building material including brickwork, windows, doors, and front porch. The roof material being proposed is nearly identical to those that currently exist on the building, and will maintain the historic appearance of the farmhouse. The colors chosen for the trim are typical of the early 1900s, and also help to maintain the historic appearance of the home.

Design Elements (Guidelines 6, 7, 9, 16). All new construction and additions shall be designed to complement the surrounding structures, the architectural style of the building, and the general design characteristics of the area, which includes porches, windows, doors, awnings, paint colors, gutters, and downspouts, by using traditional materials utilized through out the District. These elements are highly visible and are an important component of the building's visual character.

<u>Guidelines met.</u> The proposed restoration of the windows, doors, and roof, and the proposed replacement porches are compatible with the design elements established in the *Historic Dublin Design Guidelines* and appropriate to the existing structure. The two existing porches on the eastern elevation should be retained and repaired (Condition #1).

Site Considerations (Guideline 13). Building site amenities, including landscaping, fences, walls, parking areas, decks, patios, sidewalks, and street furniture, play a significant role in maintaining the character of Historic Dublin. These elements work together to maintain the District's character.

<u>Guidelines met.</u> The proposed changes are in keeping with the farmhouse character of this site the character of the surrounding area.

SECTION III – OPINION AND RECOMMENDATION: Approval with one condition. In Planning's opinion, this proposal meets the intent of the *Historic Dublin Design Guidelines*, and approval of the request is recommended with one condition.

1) The porches on the eastern façade should be retained and repaired using materials similar to those that currently exist in those areas.