

110-112 S Riverview Photos

April 13, 2021

Figure 1



Interior foundation crack at front of house

Figure 2



Crack at north wall at rear of house. Deteriorated and unsafe decking and railing.

Figure 3




Deteriorated and unsafe decking and railing.

Figure 4



Decking penetrating brick veneer. Crack in masonry and sagging lintel.

Figure 5



Deterioration of CMU foundation below brick.

Figure 6



Decking penetrating brick veneer. Crack in masonry at lintel.

Figure 7



Gap between door and brick.

Figure 8



Crack in foundation.

Figure 9



Crack in foundation and deterioration of CMU

Figure 10



Cracks in foundation and brick at south rear corner.

Figure 11



Cracks in foundation and brick at south rear corner.

Figure 12



Unevenness in roof lines

Figure 13



Unevenness in roof lines