

## Addendum # 1 -- 20-006.0-CIP -- E-Mail Coversheet 2020 Guardrail Replacement and Maintenance

<i>Planholder</i>	<i>Company E-Mail</i>	<i>Company Contact</i>
Allied Construction Industries	klane@aci-construction.org	Kayla Lane
Bid Net	gbs@bidnet.com	Bid Net
Builders Exchange	kniemeyer@bxohio.com	Kristin Niemeyer
ConstructConnect	content@constructconnect.com	Morgan Stinson
DODGE Data & Analytics	dodgedotadd@gmail.com	Dodge Data
George J. Igel & Company, Inc.	matt.check@igelco.com	Matthew Check
Lake Erie Construction	sales@lec-co.com	David Bleile
M. P. Dory	bob@mpdory.com	Bob Park
North America Procurement Council In	lyra@napc.me	ILyra de Asis
Paul Peterson Company	makr@ppco.net	Mark Rosendale
The Blue Book	kstein@mail.thebluebook.com	Kathy Stein
The Blue Book	projectleads@mail.thebluebook.com	Baishakhi Das
The Righter Company, Inc.	bill@rightercompany.com	Bill Wyner

Please sign, date and return by e-mail to [hgeorge@dublin.oh.us](mailto:hgeorge@dublin.oh.us) to verify receipt of this addendum. Attach signed copy of addendum to bid package when submitting a bid.

Received by: \_\_\_\_\_ Date: \_\_\_\_\_



Date of Addendum  
**Jun 04, 2020**

**City of Dublin -- Division of Engineering**  
5800 Shier-Rings Road Dublin OH 43016  
Phone (614) 410-4640 Fax (614) 761-650

**ADDENDUM NO. 1  
to the contract for**

**2020 GUARDRAIL REPLACEMENT AND MAINTENANCE  
20-006.0-CIP**

**Bid Date: JUNE 5, 2020**

**TO PROSPECTIVE BIDDERS: The following changes shall be made part of the contract documents for this project:**

**Request for Information:**

- 1. The limits of field painting on the Avery Rd over US 33 bridge railing are quite unclear. Do we only "touch up" where the new railing is being installed or is there more to it?*

Answer – On Sheet 12 of 13, Note 2 states "REMOVE ALL BROKEN BRACKETS AND RAILING FROM THE BRIDGE AS IDENTIFIED ON THE PLANS. IF POST IS CORRODED, THEN CLEAN ALL CORROSION OFF THE EXISTING FENCE POST DOWN TO BARE METAL AND REPAINT AS PER NOTE 5". To further clarify, if there is corrosion where the bracket is attached to the fence post, clean the bracket fence post area down to bare metal and field paint as per Note 5. Corrosion on the fence post beyond or outside of the bracket attachment area is not part of this construction project.

**Addendum Approved By:**



Paul A. Hammersmith, PE  
Director of Engineering/City Engineer

6-4-2020  
Date

\* \* \* \* \*

**Terminus for Addendum No. 1  
Certification by Bidder**

Bidder shall sign and date one copy of this Addendum No. 1 and submit with his proposal as evidence of receipt and evaluation of same in his bid analysis.

**Signed:** \_\_\_\_\_

**Date:** \_\_\_\_\_

**Company:** \_\_\_\_\_