

# OHIO HISTORIC INVENTORY

THIS IS A FACSIMILE OF THE FORM PRODUCED BY:

OHIO HISTORIC PRESERVATION OFFICE  
567 East Hudson St.  
Columbus, Ohio 43211-1030  
614/297-2470-fax 614-297-2496



OHIO  
HISTORICAL  
SOCIETY  
SINCE 1885

1.No. FRA8812-1		2.County FRANKLIN		4.Present Name(s)		<input type="checkbox"/> CODED <input type="checkbox"/> CODED		FRA - 8812-1
3.Location of Negatives CITY OF DUBLIN				5.Historic or Other Name(s)				
Roll No. 2		Picture No.(s) 7						
6.Specific Address or Location 73 S RIVERVIEW				16. Thematic Association(s)		28. No. of Stories 1.5		FRANKLIN
6a. Lot, Section or VMD Number				17. Date(s) or Period C. 1910-20		29. Basement? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
7.City or Village If Rural, Township & Vicinity DUBLIN				18. Style or Design vernacular		30. Foundation Material ROCK FACE CON. BLK		
8. Site Plan with North Arrow				18a. Style of Addition or Elements(s)		31. Wall Construction FRAME		FRANKLIN
				19. Architect or Engineer		32. Roof Type & Material GABLE/ASPH. SHNGLE		
				19a. Design Sources		33. No. of Bays Front 3 Side 4		
				20. Contractor or Builder		34. Exterior Wall Material(s) CLAPBOARD		
9. U.T.M. Reference				22. Original Use, if apparent RESIDENCE		35. Plan Shape RECT.		FRANKLIN
Quadrangle Name NW Columbus				23. Present Use RESIDENCE		36. Changes <input type="checkbox"/> Addition <input checked="" type="checkbox"/> Altered (Explain in #42) <input type="checkbox"/> Moved		
17 319960 4440550 Zone Easting Northing				24. Ownership <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private		37. Window Types <input type="checkbox"/> 6 over 6 <input type="checkbox"/> 4 over 4 <input type="checkbox"/> 2 over 2 <input checked="" type="checkbox"/> Other		
10. <input type="checkbox"/> Site <input checked="" type="checkbox"/> Building <input type="checkbox"/> Structure <input type="checkbox"/> Object				25. Owner's Name & Address, if known		38. Building Dimensions		FRANKLIN
11. On National Register? No		12. N.R. Potential?		26. Property Acreage		39. Endangered? No By What?		
13. Part of Estab. Hist. Dist? Yes		14. District Potential?		27. Other Surveys in Which Included		40. Chimney Placement OFF CENTER/ROOF		
15. Name of Established District (N.R. or Local) DUBLIN H.D. (local)				28. Other Surveys in Which Included		41. Distance from and Frontage on Road		73 S. RIVERVIEW
42. Further Description of Important Interior and Exterior Features (Continue on reverse if necessary) Modest frame residence with three-over-one windows, wood siding, an eyebrow dormer on the north side, a projecting bay on the south side and an enclosed front porch that is a later addition.						<p>PHOTO</p>		
43. History and Significance (Continue on reverse if necessary) This building, although altered, maintains the scale and residential character of S. Riverview.								
44. Description of Environment and Outbuildings (See #52) Located on a landscaped lot with a garage and shed at the rear of the property.						46. Prepared by NANCY RECCHIE		
45. Sources of Information observation						47. Organization BDR&C		
						48. Date Recorded in Field 4/03		
						49. Revised by		
						50. Date Revised		
						50b. Reviewed by		