


OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

1. No. <u>1-11-5312-1</u>		4. Present Name(s) <u>POPCOY FABRICS OF DUBLIN</u>	
2. County <u>FRANKLIN</u>		5. Other Name(s) <u>PAULUS HOUSE</u>	
3. Location of Negatives <u>MORPC</u>			
6. Specific Location <u>119 S. HIGH ST.</u>		16. Thematic Category <u>ARCHITECTURE</u>	
7. City or Town If Rural, Township & Vicinity <u>DUBLIN</u>		17. Date(s) or Period <u>1890</u>	
8. Site Plan with North Arrow 		18. Style or Design	
9. Coordinates one lot Part of H.D. Lat. _____ Long. _____ U.T.M. Reference <u>17 3V 9 840 4440 4601</u>		19. Architect or Engineer	
10. Site ☐ Building ☒ Structure ☐ Object ☐ On National Register? Yes ☐ No ☒ 12. Is It Eligible? Yes ☐ No ☐		20. Contractor or Builder <u>SAMUEL PAULUS</u>	
13. Part of Estab. Yes ☐ Hist. Dist.? No ☒ 14. District Potent'l? Yes ☐ No ☐		21. Original Use, if apparent <u>RESIDENCE</u>	
15. Name of Established District		22. Present Use <u>COMMERCIAL</u>	
		23. Ownership Public ☐ Private ☒	
		24. Owner's Name & Address, if known <u>JOHN O. MOFFITT</u> <u>185 FRANKLIN ST.</u> <u>DUBLIN</u>	
		25. Open to Public? Yes ☒ No ☐	
		26. Local Contact Person or Organization <u>DUBLIN HISTORICAL SOCIETY</u>	
		27. Other Surveys in Which Included	
		28. No. of Stories <u>2</u>	
		29. Basement? Yes ☒ No ☐	
		30. Foundation Material <u>STONE</u>	
		31. Wall Construction <u>6 COURSE BRICK / AM BOND</u>	
		32. Roof Type & Material <u>GABLE / SHINGLE</u>	
		33. No. of Bays Front <u>4</u> Side <u>4</u>	
		34. Wall Treatment <u>6 COURSE AMERICAN BOND</u>	
		35. Plan Shape <u>L</u>	
		36. Changes (Explain in #42) Addition ☐ Altered ☐ Moved ☐	
		37. Condition Interior <u>EXC.</u> Exterior <u>EXC.</u>	
		38. Preservation Underway? Yes ☒ No ☐	
		39. Endangered? By What? Yes ☐ No ☒	
		40. Visible from Public Road? Yes ☒ No ☐	
		41. Distance from and Frontage on Road <u>15' x 45'</u>	
42. Further Description of Important Features <u>L-SHAPED STRUCTURE WITH GABLE ROOF STONE LINTELS AND WINDOW SILLS WOODEN PORCH AND TWO FRAME ADDITIONS ON REAR.</u>			
43. History and Significance <u>BUILT BY SAMUEL PAULUS, A LOCAL BRICKLAYER.</u>			
44. Description of Environment and Outbuildings <u>LANDSCAPED RESIDENTIAL LOT WITH WELLHOUSE IN BACK YARD. CURBSTONE WITH "PAULUS" ON IT IN FRONT.</u>			
45. Sources of Information <u>ABSTRACT</u>		46. Prepared by <u>BASSETT / RECCHIE</u>	
		47. Organization <u>DHS / MORPC</u>	
		48. Date <u>8/76</u>	
		49. Revision Date(s)	

